



MOTOROLA

Chip Errata
DSP56001 Digital Signal Processor
Mask: B38E/B39P

ERRATA

Errata Description

Applies to Mask

1. The DSP will stop fetching instructions and will not resume operation until power is cycled if an illegal instruction (i. e. an unrecognized op code) is executed.

B38E
B39P
B77G

Freescale Semiconductor, Inc.

Chip Errata

DSP56001 Digital Signal Processor

Mask: B38E/B39P

NOTES

1. An over-bar (i.e. $\overline{\text{xxxx}}$) indicates an active-low signal.
2. The letters seen to the right of the errata tell which DSP56002 mask numbers apply.

-end-